Overdue Inspections List With All Contacts

There are 2 total objects overdue for inspection based on your search criteria.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;FIPS Code: ;Location #: ;Ins Co: State of Arizona; Status: Active; Category: Boiler; Order Results by: Location Name; Then Order by: Address;

Location ID: 990362

1 object(s)

Phone:

NOB/SIC:

Location: Florencio Lopez Laundry

Florencio Lopez Laundry, 607 E 12Th St Douglas, AZ 85607-1901

County: Cochise FIPS: 04003

Primary Contact: Florencio Lopez, Owner - Phone: 520-364-2782 - Cell: 619-852-8052

Billing Contact:

Address:

Cert Contact: Florencio Lopez, Owner - 607 E 12th St Douglas, AZ 85607-1901 - Phone: 520-364-2782 - Cell: 619-852-8052

Owner Contact:

Jur# MAWP SV Set At NB Schedule Type **Due Date Status Location** Type Use **Serial** Manufacturer Year Insurer AZ005115 WT PΒ 8893 Parker Boiler 100 150 8893 1963 State of Arizona Internal Cert 02/02/2019 Active Blrm Company

Location: Hillcrest Apts Location ID: 400030

Address: Hillcrest Apts, 1310 Hillcrest Dr Bisbee, AZ 85603 Phone: 520-432-3598 1 object(s)

County: Cochise FIPS: 04003 NOB/SIC:

Primary Contact: Jose Oliovar, Owner - Phone: 520-432-3598

Billing Contact: Cert Contact: Owner Contact:

MAWP SV Set At NB Jur# Type Use **Serial** Manufacturer Year Insurer Schedule Type **Due Date Status Location** AZ011964 WT SH 15 18908 Parker Boiler 1974 State of Arizona **Basement Boiler** 15 18908 Internal Cert 09/14/2018 Active Company Room

TOTAL OBJECTS 2
TOTAL LOCATIONS 2