Overdue Inspections List With All Contacts

There are total objects overdue for inspection based on your search criteria. 2 Search Criteria: NOB/SIC: :Address 1: :City: :Zip: :FIPS Code: :Location #: :Ins Co: State of Arizona: Status: Active: Order Results by: Location Name: Then Order by: Address: Location: Florencio Lopez Laundry Location ID: 990362 Florencio Lopez Laundry, 607 E 12Th St Douglas, AZ 85607-1901 Phone: Address: 1 object(s) Cochise FIPS: 04003 NOB/SIC: County: Primary Contact: Florencio Lopez, Owner - Phone: 520-364-2782 - Cell: 619-852-8052 **Billing Contact: Cert Contact:** Florencio Lopez, Owner - 607 E 12th St Douglas, AZ 85607-1901 - Phone: 520-364-2782 - Cell: 619-852-8052 **Owner Contact:** Jur# MAWP SV Set At NB Schedule Type Due Date Status Location Type Use **Serial** Manufacturer Year Insurer AZ005115 WΤ PB 8893 Parker Boiler 100 150 8893 1963 State of Arizona Internal Cert 02/02/2019 Active Blrm Company Location: Hillcrest Apts Location ID: 400030 Hillcrest Apts, 1310 Hillcrest Dr Bisbee, AZ 85603 Phone: Address: 520-432-3598 1 object(s) NOB/SIC: County: Cochise FIPS: 04003 Primary Contact: Jose Oliovar, Owner - Phone: 520-432-3598 **Billing Contact: Cert Contact: Owner Contact:** MAWP SV Set At NB Jur# Type Use Serial Manufacturer Year Insurer Schedule Type **Due Date Status Location** AZ011964 WΤ SH 15 18908 Parker Boiler 1974 State of Arizona Internal Cert **Basement Boiler** 15 18908 09/14/2018 Active Company Room TOTAL OBJECTS 2

TOTAL LOCATIONS 2