

# Overdue Inspections List With All Contacts

There are 1 total objects overdue for inspection based on your search criteria.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;FIPS Code: ;Location #: ;Ins Co: State of Arizona; Status: Active; Use: JSK~PB~PB/HW~SH; Order Results by: Location Name; Then Order by: Address;

**Location:** Hillcrest Apts **Location ID:** 400030  
**Address:** Hillcrest Apts, 1310 Hillcrest Dr Bisbee, AZ 85603 **Phone:** 520-432-3598 1 object(s)  
**County:** Cochise **FIPS:** 04003 **NOB/SIC:**  
**Primary Contact:** Jose Olioivar, Owner - Phone: 520-432-3598  
**Billing Contact:**  
**Cert Contact:**  
**Owner Contact:**

<u>Jur#</u>	<u>Type</u>	<u>Use</u>	<u>MAWP</u>	<u>SV</u>	<u>Set At</u>	<u>NB</u>	<u>Serial</u>	<u>Manufacturer</u>	<u>Year</u>	<u>Insurer</u>	<u>Schedule Type</u>	<u>Due Date</u>	<u>Status</u>	<u>Location</u>
AZ011964	WT	SH	15	15	18908	18908	Parker Boiler Company	1974	State of Arizona	Internal Cert	09/14/2018	Active	Basement Boiler Room	

**TOTAL OBJECTS** 1

**TOTAL LOCATIONS** 1