Overdue Inspections List With All Contacts

There are total objects overdue for inspection based on your search criteria. Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;FIPS Code: ;Location #: ;Ins Co: State of Arizona; Status: Active; Category: Boiler; Order Results by: Location Name; Then Order by: Address; **Brackers Dept Store** Location: Location ID: 253709 Brackers Dept Store, 68 N Morley Ave Nogales, AZ 85621-3114 Address: Phone: 1 object(s) County: Santa Cruz FIPS: 04023 NOB/SIC: Primary Contact: Jaime Cervantes - Phone: 520-287-3631 **Billing Contact: Cert Contact:** Bruce Bracker, Owner - PO Box 1489 Nogales, AZ 85628-1489 - Phone: 520-287-3631 **Owner Contact:** Jur# MAWP SV Set At NB **Serial** Manufacturer Year Insurer Schedule Type **Due Date** Status Location Type Use AZ012457 WΤ PΒ 100 480 561 1997 State of Arizona External Non-Cert 11/10/2016 Active Basement 100 General

TOTAL OBJECTS **TOTAL LOCATIONS** 1

1