Overdue Inspections List With All Contacts

There are 1 total objects overdue for inspection based on your search criteria.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;FIPS Code: ;Location #: ;Ins Co: State of Arizona; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location ID: 253709

1 object(s)

Phone:

NOB/SIC:

Location: Brackers Dept Store

Brackers Dept Store, 68 N Morley Ave Nogales, AZ 85621-3114

County: Santa Cruz FIPS: 04023

Primary Contact: Jaime Cervantes - Phone: 520-287-3631

Billing Contact:

Address:

Cert Contact: Bruce Bracker, Owner - PO Box 1489 Nogales, AZ 85628-1489 - Phone: 520-287-3631

Owner Contact:

Jur# MAWP SV Set At NB **Serial** <u>Manufacturer</u> Year Insurer **Schedule Type Due Date Status Location Type** <u>Use</u> AZ012457 WT PΒ 100 480 561 1997 State of Arizona External Non-Cert 11/10/2016 Active Basement 100 General

TOTAL OBJECTS 1
TOTAL LOCATIONS 1

7/31/2019 9:31:20 AM JURISDICTION ONLINE Page 1 of 1
Copyright © 2019 Praeses, LLC.